




Safety precautions



Crushed venting is one of the most common causes of dryer fires and maintenance calls.

Vinyl and foil venting material easily collapse and burn in the event of a fire.

Reduced Airflow

Reduced airflow and the resulting lint build-up cause overheating by preventing fast enough drying action.

When this happens, the high temperature limit safety switch has to cycle on and off to control the heater.

**FLAME
RESISTANT
ALL METAL
CONSTRUCTION**



Builder's Best® Venting

Proper venting materials can decrease drying time and decrease operating costs by helping the dryer achieve maximum performance.

Builder's Best enhances the safety of your appliance with sturdy build quality that ensure optimum airflow.

**ENHANCED
DRYER
EFFICIENCY
AND LIFESPAN**



**MEETS
DRYER
MANUFACTURER
RECOMMENDATIONS**



Builder's Best, Inc.
201 Broiles Drive • Jacksonville TX 75766
1-8-U VENT SAFE • buildersbest.com
©2016 tearsheetsafetyprecautionsV3

